File Original and First Copy with Department of Ecology
Second Copy — Owner's Copy

Start Card No. (W0727 66

| UNIQUE | WELL 1.D. # | | |
|------------|-------------|------|---|
| mit No. 31 | -1E- | - 12 | J |

| | Copy — Driller's Copy STATE OF W | Water Fight Perhit No | | <u></u> |
|---------------|---|---|--|--------------------------------|
| | | P.O. BX 969 FREE/AND WA | | |
| (2) | LOCATION OF WELL: County 15LAND | NE 1/4 SE 1/4 Sec 1 2 T | 3 N. R_ | <u>E</u> w.M. |
| (2a) | STREET ADDRESS OF WELL (or nearest address) | WELCHER RD, COUPEY, ILE | <u>um 98</u> | 239 |
| $\overline{}$ | PROPOSED USE: Domestic Industrial Municipal | (10) WELL LOG or ABANDONMENT PROCEDURE | DESCRIPTIO | MC |
| | ☐ Irrigation ☐ DeWater Test Well ☐ Other ☐ | Formation: Describe by color, character, size of material and structure, as and the kind and nature of the material in each stratum penetrated, with change of information. | nd show thickness h at least one en | s of aquiters itry for each |
| (4) | TYPE OF WORK: Owner's number of well (If more than one) | MATERIAL | FROM | то |
| | Abandoned New well | SANDY HARD PAN | 0 | 22 |
| | Deepened ☐ Cable_M Driven☐ Reconditioned ☐ Rotary ☐ Jetted ☐ | CIAV | 22 | <u>73</u> |
| (5) | DIMENSIONS: Diameter of well Inches. | HARO PAN | | 82 |
| (0) | Drilled 238 feet. Depth of completed well 238 ft. | SANDY CLAY | 82 | 135 |
| | ACMETALICATION DETAILS. | <u>Clay</u> | 135 | <u>152</u> 156 |
| (6) | CONSTRUCTION DETAILS: Casing installed: | SAND | | 232 |
| | Welderd At Diam from It to It. | WATER IN GRAVEL MIX | | 238 |
| | Liner installed Threaded Dism. from ft. to ft. | COMITE IN GRAVED IMA | | |
| | Perforations: Yes No 🔀 | | | |
| | Type of perforator used | | | |
| | SiZE of perforationsin. byin. | | | |
| | | | | |
| | perforations from ft. to ft | | + - + | |
| | | | 1 | |
| | Screens: Yes No Wanufacturer's Name | | | |
| | Type STAINIESS STEEL Model No. | | L E D | |
| | Diam. La Slot size 14 from 233 ft. to 238 ft. | | | |
| | DiamSlot sizeft. toft. | SEP 1 | 2 1997 | |
| | Gravel packed: Yes No 🗷 Size of gravel | JL: 1 |). 1001 | |
| | Gravel placed fromft. toft. | 4, 7 | - 🖟 ਹ L ਹ ਪ ੀ | Y |
| | Surface seal: Yes 🗷 No 🗌 To what depth? 20+ ft. | | | |
| | Material used in seal | | | |
| | Did any strata contain unusable water? Yes No. | | | |
| | Type of water? Depth of strata Method of sealing strata off | | | |
| | Method of Seaming Strata on | | | |
| (7) | PUMP: Manufacturer's Name H.P. | | | |
| | туре | Work Starter 12 AC 197 Completed | .1. 3 | .19 9 |
| (8) | SDOAB LINGS BAS 19AGI | 77377 02772 | | <u></u> |
| | Static level | WELL CONSTRUCTOR CERTIFICATION: | | |
| | Actorian water is controlled by | I constructed and/or accept responsibility for construction stand compliance with all Washington well construction stand | tion of this we | ell, and its |
| _ | (Cap. valve, etc.) | the information reported above are true to my best know | ledge and beli€ | əf. |
| (9) | WELL TESTS: Drawdown is amount water level is lowered below static level Was a pump test made? Yes | WALL AND THE MELL D | PILIE | 29 |
| | Was a pump test made? Yes No. If yes, by whom?hrs. Yield: | NAME (PERSON, FIRM, OR CORPORATION) (TYP | | |
| | 11 11 11 | Address OAK HARBOR WA | 982 | <u> </u> |
| _ | n n n n | | cense No /a | 29 |
| _ | Recovery data (time taken as zero when pump turned off) (water level measured from well | (Signed) (WELL DRILLER) | | |
| | top to water level) Time Water Level Time Water Level Time Water Level | Contractor's | | |
| _ | | Registration | <u> </u> | _, 19 <i>9</i> _; |
| _ | | (USE ADDITIONAL SHEETS IF NECE | , | . / |
| _ | Date of test | | | |
| | Bailer testgal./min, withft. drawdown afterhrs. | Feology is an Equal Opportunity and Affirmative Act | tion employer | r. For spe |
| | Airtest gal./min, with stem set at ft. for hrs. | cial accommodation needs, contact the Water Reso | urces Program | m at (206 |
| | Artesian flowg.p.m. Date | 407-6600. The TDD number is (206) 407-6006. | | |